



## Appendix 4B: Photo Register





Photo 1: Field drain along northern boundary of field 13



Photo 2: Ditch located between field 12 and 13





Photo 3: Watercourse along northern boundary of field 12, c.2.5m deep and 4m wide with running water.



Photo 4: Ditch located along the border of fields 11 and 12





Photo 5: northern section of field 11 which suffers from waterlogging (area avoided)



Photo 6: Field 10 is slightly marshy, however lying water was minimal





Photo 7: Surface water c. 200mm deep in southeast of field 10 (marshy area avoided)



Photo 8: Drain that runs along northern boundary of field 4, c. 2m wide and 3m deep.





Photo 9: Field drain that runs between fields 4 and 5



Photo 10: Watercourse that runs between fields 3 and 4





Photo 11: Field drain along eastern boundary of field 3



Photo 12: Watercourse along the southern boundary of field 5





Photo 13: Watercourse fenced off along northern boundary of field 28



Photo 14: Watercourse along northern boundary of field 28





Photo 15: Watercourse between fields 25 and 27, c. 4m deep and 10m wide. Potential flooding as low point.



Photo 16: Low part of field 25 which is marshy (area avoided)





Photo 17: Watercourse between fields 24 and 25, c. 2.5m deep



Photo 18: Fenced off low point of field 24 (Area avoided)





Photo 19: Old borrow pit in field 24 (area avoided)



Photo 20: Fenced off marsh area in field 24 (Area avoided)





Photo 21: Field drain between fields 16 and 17



Photo 22: Ridge on eastern side of field 16





Photo 23: Field drain between fields 15 and 16



Photo 24: Standing water in field drain along northeast boundary of field 15





Photo 25: Watercourse along northern boundary of field 15, with the image taken in the field to the west.



Photo 26: Photo of Derril Water. Approximately 3m deep, 5m wide, with water at 0.5m depth and fast flowing.

