




## Appendix 7F: Visibility Assessment Evidence




## Residential Receptors


### Receptor 1





Receptor 2 and 3



Receptor 4



Receptor 5



Receptor 6 - 8



Receptor 9




Receptor 10 and 11







Receptor 12 and 13



Receptor 14




Receptor 15 and 16



Receptor 17 and 18



Receptor 19 and 20



Receptor 21 – 24



Receptor 25 and 26



Receptor 27 and 28







Receptor 29




Receptor 30



Receptor 31 and 32




Receptor 33 and 34



Receptor 35




Receptor 38 – 40





Receptor 41







Receptor 42 and 43




Receptor 44




## Road Receptors


### Receptor 1




Receptor 2




Receptor 3



Receptor 7




Receptor 8







Receptor 9



Receptor 10




Receptor 11




Receptor 12

East Facing




West Facing




Receptor 13

East Facing




West Facing




Receptor 14

East Facing






West Facing



Receptor 15

East Facing




West Facing




Receptor 16


East Facing




West Facing




Receptor 17



Receptor 18




Receptor 19







Receptor 20




Receptor 21




Receptor 22




Receptor 23




Receptor 24




Receptor 25



Receptor 26




Receptor 27








Receptor 28




Receptor 29




Receptor 30




Receptor 31




Receptor 32



Receptor 33



Receptor 34



Receptor 35

